





## Clean Water Act Section 404: Site Visit/Case Development

For inspections authorized pursuant to Clean Water Act sections 308 and 404 (33 U.S.C. §§ 1318 and 1344)

This report includes only factual information gained by documentation, onsite observations, and/or onsite interviews.

Inspector Name(s)	Stephanie Andreescu Seika Robinson (in-training) Austin Jepsky (in-training)	Time In	10:32 AM	Start Date	October 20, 2022
		Time Out	10:50 AM	End Date	October 20, 2022
Inspector's Organization	U.S. EPA Region 2				
Organization Requesting Inspection (if different)					
Inspection Type	CWA Section 404 Inspection	Inspection Status	Original		
Site Name	(b) (6) Property				
Site Address*	430 Stony Ford Road (Tax ID 61-1-5.225)				
City*	Wallkill, Middletown	County*	Orange	State*	NY
				Zip Code*	10941
Latitude/Longitude*	41.4587, -74.3154	Estimated Size of Site (acres)	44.40		
Is there a home on the site?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No				
Inspector Signature	 Digitally signed by STEPHANIE ANDREESCU Date: 2022.12.08 14:36:24 -05'00'			Date	12/8/22
Supervisor Signature	 Digitally signed by Finocchiaro, Marco Date: 2022.12.09 09:43:32 -05'00'			Date	12/8/12

## Clean Water Act Section 404: Site Visit/Case Development

For inspections authorized pursuant to Clean Water Act sections 308 and 404 (33 U.S.C. §§ 1318 and 1344)

Site Name	<div style="border: 1px solid black; padding: 2px;"> <b>(b) (6)</b> Property         </div>	Start Date	<div style="border: 1px solid black; padding: 2px;">October 20, 2022</div>
		End Date	<div style="border: 1px solid black; padding: 2px;">October 20, 2022</div>
Inspection Purpose	<div style="border: 1px solid black; padding: 2px;">Initial site visit</div>		
<b>Opening Conference</b>			
<input checked="" type="checkbox"/> Presentation of Inspector Credentials Name and Title (Use N/A if owner/operator not available to join the inspection)			
<div style="border: 1px solid black; padding: 2px;">         Credentials were presented to <b>(b) (b) (6)</b> (property owner)       </div>			
<input checked="" type="checkbox"/> Opening Conference Name of person authorizing access if applicable			
<div style="border: 1px solid black; padding: 2px;">         I spoke with <b>(b) (6)</b> over the phone to arrange the inspection.       </div>			
Notes from Opening Conference			
<div style="border: 1px solid black; padding: 2px;">         We explained the reason for the inspection and the pointed out the area that we were interested in inspecting.       </div>			
<input type="checkbox"/> Access Issues if Any Describe			
<b>Inspection Observations and Sample Collection</b>			
Site Owner* (Name, title and contact information)			
<div style="border: 1px solid black; padding: 2px;"> <b>(b) (b) (6)</b>   <b>(b) (6)</b> </div>			
Additional Persons Present at Inspection			
<div style="border: 1px solid black; padding: 2px;">N/A</div>			
General Site Characteristics (layout of property, etc.)			
<div style="border: 1px solid black; padding: 2px;">         The Site is comprised of a 44.40-acre parcel with frontage and access along Stony Ford Road on the south side of the property. Two mapped unnamed tributaries to the Wallkill River flow through the Site. The majority of the Site is forested and undeveloped. Potential wetland areas were observed on the property. A single family home and attendant structures are located along Stony Ford Road.       </div>			
Site Overview (Past inspections, site description, permits, etc.)			
<div style="border: 1px solid black; padding: 2px;">         EPA's Wetland Protection Section had not visited the site prior to this inspection.       </div>			
Scope of Inspection (Areas inspected or not inspected)			
<div style="border: 1px solid black; padding: 2px;">         EPA's inspection was limited to the southwestern portion of the parcel where piles of dirt and rock had been placed at the edge of a lawn near a wooded area.       </div>			
Environmental Conditions (e.g., wind, rain, smoke, dust, temperature, snow)			
<div style="border: 1px solid black; padding: 2px;">         Sunny, high 40's       </div>			

## Clean Water Act Section 404: Site Visit/Case Development

For inspections authorized pursuant to Clean Water Act sections 308 and 404 (33 U.S.C. §§ 1318 and 1344)

Site Name	(b) (6) Property	Start Date	October 20, 2022
		End Date	October 20, 2022

**Field Work Conducted**

Data recorded during the inspection included photographs and handwritten notes.

EPA met with (b) (6) and then proceeded to the southwestern portion of the Site where piles of fill material consisting of dirt and rock had been placed into piles at the edge of a lawn.

EPA walked around the fill piles. Vegetation near the piles included red oak trees (*Quercus rubra*) and other upland vegetation. Wetland indicators were not observed adjacent to the fill piles. Potential wetland areas were located further west.

**Closing Conference**

Documents Received and/or Requested During the Inspection

N/A

Compliance Assistance Provided (If any)

N/A

Observations Relayed to Site Owner/Operator

N/A

Actions Taken by Owner/Operator During the Inspection (If any)

N/A

Potential Issues of Concern Including Regulatory Citations

N/A

**Attachments\***

☐ Maps and Sketches

☒ Photographs (including location) and Photo Log

☐ Other

**Additional Notes**

CWA 404 Inspection Photolog

(b) (6)

Property

430 Stony Ford Road, Wallkill  
Orange County, NY

October 20, 2022






**Date:** 10/20/2022  
**Time:** 10:37 AM  
**Photographer:** S. Robinson  
**Photo ID:** 1 – PA200498

**Description:**

Piles of fill material on property





**Date:** 10/20/2022  
**Time:** 10:38 AM  
**Photographer:** S. Robinson  
**Photo ID:** 2 – PA200499

**Description:**

Wooded area behind fill piles;  
potential wetland in the  
background





**Date:** 10/20/2022  
**Time:** 10:38 AM  
**Photographer:** S. Robinson  
**Photo ID:** 3 – PA200500

**Description:**

Fill piles near wooded area





**Date:** 10/20/2022  
**Time:** 10:39 AM  
**Photographer:** S. Robinson  
**Photo ID:** 4 – PA200501

**Description:**  
Fill piles on property






**Date:** 10/20/2022  
**Time:** 10:40 AM  
**Photographer:** S. Robinson  
**Photo ID:** 5 – PA200502

**Description:**  
Fallen tree





**Date:** 10/20/2022  
**Time:** 10:40 AM  
**Photographer:** S. Robinson  
**Photo ID:** 6 – PA200503

**Description:**  
Wooded area on property





**Date:** 10/20/2022  
**Time:** 10:42 AM  
**Photographer:** S. Robinson  
**Photo ID:** 7 – PA200504

**Description:**

Fill piles next to wooded area on property





**Date:** 10/20/2022  
**Time:** 10:47 AM  
**Photographer:** S. Robinson  
**Photo ID:** 8 – PA200505

**Description:**

Fill piles on property located  
between lawn and wooded area